



TAKE THE TACHOMETER SIGNAL FROM ONE OF THREE WHITE AC CHARGING WIRES.

Note: LONGER PLUG WIRE IS FOR THE CENTER SPARK PLUG

Note: LONGER PLUG WIRE IS FOR THE CENTER SPARK PLUG  
 Note: GROUNDING IS CRITICAL FOR PROPER OPERATION. IT IS STRONGLY RECOMMENDED THAT ALL GROUNDING BE CONNECTED TO ONE OF THE TWO STARTER MOTOR MOUNTING BOLTS.

**Optional components**

Item & Notes	P/N Specification	Supplier
Tachometer (monitor Engine RPM)	04Y-352	HKS
MGL w/Senders (monitor Exhaust Gas Temp, Cylinder Head Temp, Oil Temp, and Oil Pressure)	07Z-002	HKS
Carburetor Heaters Used when operating temperature is below 5deg C. Will maintain stable engine idling at low temperature	04Y-289	HKS

**Required components, not provided with Engine**

Item	Specification	Recommended	Supplier
12VDC Battery	BATTERY (MIN 10 AMP HOUR)	Smaller Batter, Wesco 12V7 or greater	
Starter Solenoid	Common Ford Auto Part	SAZ4201AD	Prestolite
Fuel Pump	Low pressure 2-4PSI (required if engine is at or below fuel source)	40105	Facet

TITLE		REVISIONS	
HKS 700E INSTALLATION WIRING OPTIONS WIRING		NO.	DATE
		1	11/08
DATE ORIGINAL		SCALE	
2008-10			
LATEST REVISION	JOB NO.	CHECKED	DRAWN
2008-11			FORD

